


平成 25 年度 農林水産常任委員会 第 2 回管内視察の概要

■視察日時 平成 26 年 2 月 26 日(水) 午後 0 時 2 0 分から午後 4 時 3 0 分まで

■視察の概要

	視察内容	視察の様子
視察先・阿蘇郡高森町河原地区	阿蘇郡高森町河原地区のナス(ヒゴムラサキ)ビニールハウスの倒壊現場、	 <p>A photograph showing several collapsed plastic greenhouses in a field. A group of people, including some in blue and yellow jackets, are standing in the muddy ground, observing the damage. The background shows a forested hillside under an overcast sky. A date stamp '2014 02 26' is visible in the bottom right corner.</p>
	農林水産常任委員会による高森町河原地区の降雪による被害現場の視察と、被災者からの被害内容の聴取	 <p>A photograph of a group of people standing outdoors in a snowy area. Many are holding umbrellas, suggesting it might be raining or snowing. A red bus is partially visible in the background. The people are dressed in winter clothing. A date stamp '2014 02 26' is visible in the bottom right corner.</p>
	高森町河原地区の畜舎の大雪による被害の状況	 <p>A photograph showing a large, partially collapsed barn or shed almost completely buried in deep snow. The structure's roof and walls are heavily laden with snow, and the surrounding area is a flat expanse of white. A date stamp '2014 02 26' is visible in the bottom right corner.</p>